




ÉKSZÍJAK HOSSZMÉRET KÜLÖNBSÉGEI



La >>> külső kerületi hossz
 Lp, Lw, Ld, Le >>> névleges kerületi hossz
 Li >>> belső kerületi hossz

Profilok	Mért hossz jele	La=Li+ (mm)	La=Lp+ (mm)	Lp=Li+ (mm)
	Li	31	12	19
	XPZ, SPZ / Lp AVX10, 9,5x / La	51	13	38
	Z/10 / Li ZX / Lp	38	16	22
	XPA, SPA / Lp AVX13, 12,5 / La	63	18	45
	AX / Lp A/13 / Li	50	20	30
	XPB, SPB / Lp HB / La	82 (HB 62)	22 (HB 22)	60 (HB 66)
	BX / Lp B/17 / Li	69	29	40
	Li	79	31	48
	Lp	113	30	83
	CX / Lp C/22 / Li	88	30	58
	Li	100	36	61
	Li	126	51	75
	Li	157	77	80
	Li	138	58	80